




## WELLHEAD ABANDONMENT FORM

<b>SITE NAME:</b> BADDING USX W25-07D							<b>DATE:</b> 6/10/2021	<b>REM. PROJECT #:</b> 90359152	<b>WEATHER:</b> SUNNY 75 F		
<b>SITE DIRECTIONS:</b> CR 37 AND CR 18, S 2/10, W 2/10 INTO							<b>CLIENT:</b> Oxy				
<b>LEGALS AND LAT/LONG:</b> 40/1135128, -104.7195138							<b>TASMAN PERSONNEL:</b> Matt Rianda				
<b>SOIL TYPES:</b> Clayey Sand - SC							<b>SURFACE GRADIENT:</b> Southwest				
SOIL SAMPLING							FACILITY INFRASTRUCTURE				
Date/Time	Soil Sample ID	PID (ppm)	Visual	Olfactory	Photo?	Grab or Lab Sample?	EQUIPMENT		Quantity		
							Above Ground Storage Tank (AST)				
6/10/2021 10:57	WH-B01@5'	8.1	No Staining	No Odor	Yes	Lab	Buried or Partially Buried Vessel				
6/10/2021 11:00	WH-N01@4'	1.7	No Staining	No Odor	Yes	N/A	Separator				
6/10/2021 11:03	WH-S01@4'	0.6	No Staining	No Odor	Yes	N/A	Emission Control Device (ECD)				
6/10/2021 11:06	WH-E01@4'	0.3	No Staining	No Odor	Yes	N/A	Dump Line				
6/10/2021 11:09	WH-W01@4'	0.3	No Staining	No Odor	Yes	N/A	Wellhead		1		
6/10/2021 11:12	WHS-N01@3"	0.0	No Staining	No Odor	Yes	N/A	Flowline				
6/10/2021 11:15	WHS-S01@3"	0.0	No Staining	No Odor	Yes	N/A	Other:				
6/10/2021 11:18	WHS-E01@3"	0.0	No Staining	No Odor	Yes	N/A	Soil Loads Removed				
6/10/2021 11:21	WHS-W01@3"	0.0	No Staining	No Odor	Yes	N/A	<b>IMPACTED SOIL IDENTIFIED?</b>				
6/10/2021 11:24	WH-BG01@5'	0.2	No Staining	No Odor	Yes	Lab	<b>ESTIMATED VOLUME OF IMPACTS:</b>				
							Date	Number	CY		
							<b>Total Removed</b>		0	0	
							<b>Disposal Facility:</b>				
							Groundwater Recovery				
							<b>DATE GW ENCOUNTERED:</b>			<b>DEPTH:</b>	
							<b>GROUNDWATER IN CONTACT WITH IMPACTED SOIL?</b>				
							<b>LNAPL OR SHEEN OBSERVED ON GW?</b>				
GROUNDWATER SAMPLING							Date		BBLs		
Date/Time	Groundwater Sample ID	Depth Collected	Turbid?	Sheen?	Odor?	Photo?					
6/10/2021 11:58	GW01	5	Medium Turbidity	None	None	Yes					
							<b>Total Removed</b>		0		
							<b>Disposal Facility:</b>				

Photographic Log



Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions:			

Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions: LOOKING SOUTH			

**Photographic Log**



Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions:			

Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions:			

**Photographic Log**



<b>Equipment ID:</b>		<b>Equipment Type:</b>	
<b>Material:</b>	<b>Volume:</b>	<b>Contents:</b>	
<b>Notes/Conditions:</b>			

<b>Equipment ID:</b>		<b>Equipment Type:</b>	
<b>Material:</b>	<b>Volume:</b>	<b>Contents:</b>	
<b>Notes/Conditions:</b>			

### Photographic Log



<b>Equipment ID:</b>		<b>Equipment Type:</b>		<b>Equipment ID:</b>		<b>Equipment Type:</b>	
<b>Material:</b>	<b>Volume:</b>	<b>Contents:</b>		<b>Material:</b>	<b>Volume:</b>	<b>Contents:</b>	
<b>Notes/Conditions:</b> LOOKING SOUTH				<b>Notes/Conditions:</b>			