

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402721862

Date Received:

06/17/2021

Spill report taken by:

GINTAUTAS, PETER

Spill/Release Point ID:

480179

**SPILL/RELEASE REPORT (INITIAL /w SUPPLEMENTAL)**

This form is to be submitted by the party responsible for the oil and gas spill or release. Refer to COGCC Rule 906.b. for reporting requirements of spills or releases of E&P Waste or produced fluids. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

**OPERATOR INFORMATION**

Name of Operator: <u>KERR MCGEE OIL &amp; GAS ONSHORE LP</u>	Operator No: <u>47120</u>	<b>Phone Numbers</b>
Address: <u>P O BOX 173779</u>		Phone: <u>(970) 336-3500</u>
City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80217-3779</u>		Mobile: <u>(970) 515-1698</u>
Contact Person: <u>Gregory Hamilton</u>		Email: <u>Gregory.Hamilton@ox.com</u>

Transfer of Operatorship: Pursuant to Rule 912.f, this Supplemental Form 19 is being submitted to designate the Buying Operator as the responsible Operator for this Spill and Release.

**INITIAL SPILL/RELEASE REPORT**

Initial Spill/Release Report Doc# 402721862

Initial Report Date: 06/17/2021 Date of Discovery: 06/17/2021 Spill Type: Historical Release

**Spill/Release Point Location:**

QTRQTR NENE SEC 25 TWP 2N RNG 66W MERIDIAN 6

Latitude: 40.113531 Longitude: -104.719523

Municipality (if within municipal boundaries): \_\_\_\_\_ County: WELD

Enter Lat./long measurement of the actual Spill/Release Point. Lat./Long. Data shall meet standards of Rule 216.

**Reference Location:**

Facility Type: WELL  Facility/Location ID No \_\_\_\_\_  
 Spill/Release Point Name: BADDING USX W 25-07D Release  Well API No. (Only if the reference facility is well) 05-123-33608  
 No Existing Facility or Location ID No.

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): <u>Unknown</u>	Estimated Condensate Spill Volume(bbl): <u>Unknown</u>
Estimated Flow Back Fluid Spill Volume(bbl): <u>0</u>	Estimated Produced Water Spill Volume(bbl): <u>Unknown</u>
Estimated Other E&P Waste Spill Volume(bbl): <u>0</u>	Estimated Drilling Fluid Spill Volume(bbl): <u>0</u>

Specify: \_\_\_\_\_

Has the subject Spill/Release been controlled at the time of reporting? Yes

**Land Use:**

Current Land Use: NON-CROP LAND Other(Specify): \_\_\_\_\_  
 Weather Condition: Fair ~ 95 degrees F.  
 Surface Owner: FEE Other(Specify): \_\_\_\_\_

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

Historical soil impacts were discovered following cut and cap operations at the Badding USX W 25-07D wellhead location. The release became State reportable on June 17, 2021, due to the quantity of impacted soil excavated. A topographic Site Location Map showing the geographic setting of the release is provided as Figure 1.

**List of Agencies and Other Parties Notified Pursuant to Rule 912.b.(7)-(11):**

**OTHER NOTIFICATIONS**

<u>Date</u>	<u>Agency/Party</u>	<u>Contact</u>	<u>Phone</u>	<u>Response</u>
6/17/2021	County	Roy Rudisill	-email	
6/17/2021	County	Jason Maxey	-email	
6/17/2021	Private	Landowner	-phone	

**REPORT CRITERIA**

**Rule 912.b.(1) Report to the Director (select all criteria that apply):**

No Rule 912.b.(1).A: A Spill or Release of any size that impacts or threatens to impact any Waters of the State, Public Water System, residence or occupied structure, livestock, wildlife, or publicly-maintained road.  
 Waters of the State: \_\_\_\_\_ Public Water System: \_\_\_\_\_  
 Residence or Occupied Structure: \_\_\_\_\_ Livestock: \_\_\_\_\_  
 Wildlife: \_\_\_\_\_ Publicly-Maintained Road: \_\_\_\_\_

No Rule 912.b.(1).B: A Spill or Release in which 1 barrel or more of E&P Waste or produced fluids is spilled or released outside of berms or other secondary containment.

No Rule 912.b.(1).C: A Spill or Release of 5 barrels or more of E&P Waste or produced Fluids regardless of whether the Spill or Release is completely contained within berms or other secondary containment.

No Rule 912.b.(1).D: Within 6 hours of discovery, a Grade 1 Gas Leak. For a Grade 1 Gas Leak from a Flowline, the Operator also must submit the Form 19 – Initial, document number on a Form 44, Flowline Report, for the Grade 1 Gas Leak  
 Enter the approximate time of discovery \_\_\_\_\_ (HH:MM)  
 Enter the Document Number of the Grade 1 Gas Leak Report, Form 44 \_\_\_\_\_  
 Was there a reportable accident associated with either a Grade 1 Gas Leak or an E&P waste spill or release? \_\_\_\_\_  
 Enter the Document Number of the Initial Accident Report, Form 22 \_\_\_\_\_  
 Was there damage during excavation? \_\_\_\_\_  
 Was CO 811 notified prior to excavation? \_\_\_\_\_

Yes Rule 912.b.(1).E: The discovery of 10 cubic yards or more of impacted material resulting from a current or historic Spill or Release. Discovery and reporting will not be contingent upon confirmation samples demonstrating exceedance of Table 915-1 standards.  
 Estimated Volume of Impacted Solids (cu. yd.): 40

No Rule 912.b.(1).F: The discovery of impacted Waters of the State, including Groundwater. Discovery and reporting will not be contingent upon confirmation samples demonstrating exceedance of Table 915-1 standards. The presence of free product or hydrocarbon sheen on Groundwater or surface water is reportable. The presence of contaminated soil in contact with Groundwater or surface water is reportable. Check all that apply:

The presence of free product or hydrocarbon sheen Surface Water  
 The presence of free product or hydrocarbon sheen on Groundwater  
 The presence of contaminated soil in contact with Groundwater  
 The presence of contaminated soil in contact with Surface water

Yes	Rule 912.b.(1).G: A suspected or actual Spill or Release of any volume where the volume cannot be immediately determined, including a spill or release of any volume that daylight from the subsurface.
No	Rule 912.b.(1).H: Spill or Release resulting in vaporized hydrocarbon mists that leave the Oil and Gas Location or Off-Location Flowline right of way from an Oil and Gas Location and impacts or threatens to impact off-location property.
	<input type="checkbox"/> Areas offsite of Oil & Gas Location <input type="checkbox"/> Off-Location Flowline right of way
No	Rule 912.b.(1).I: A Release of natural gas that results in an accumulation of soil gas or gas seeps.
No	Rule 912.b.(1).J: A Release that results in natural gas in Groundwater.

### SPILL/RELEASE DETAIL REPORTS

#1	Supplemental Report Date: <u>06/17/2021</u>		
<b>FLUIDS</b>	BBL's SPILLED	BBL's RECOVERED	Unknown
OIL	_____	_____	<input checked="" type="checkbox"/>
CONDENSATE	_____	_____	<input checked="" type="checkbox"/>
PRODUCED WATER	_____	_____	<input checked="" type="checkbox"/>
DRILLING FLUID	<u>0</u>	<u>0</u>	<input type="checkbox"/>
FLOW BACK FLUID	<u>0</u>	<u>0</u>	<input type="checkbox"/>
OTHER E&P WASTE	<u>0</u>	<u>0</u>	<input type="checkbox"/>
specify: _____			
Was spill/release completely contained within berms or secondary containment? <u>NO</u> Was an Emergency Pit constructed? <u>NO</u>			
<i>Secondary containment, including walls &amp; floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.</i>			
<b>A Form 15 Pit Report shall be submitted within 30 calendar days after the construction of an emergency pit</b>			
Impacted Media (Check all that apply) <input checked="" type="checkbox"/> Soil <input type="checkbox"/> Groundwater <input type="checkbox"/> Surface Water <input type="checkbox"/> Dry Drainage Feature			
Surface Area Impacted: Length of Impact (feet): <u>9</u>		Width of Impact (feet): <u>8</u>	
Depth of Impact (feet BGS): <u>5</u>		Depth of Impact (inches BGS): _____	
How was extent determined?			
<p>Following cut and cap operations on June 10, 2021, a confirmation soil sample (WH-B01@5') was collected from the base of the wellhead cut and cap excavation area and submitted for laboratory analysis of benzene, toluene, ethylbenzene, total xylenes (BTEX), naphthalene, and total petroleum hydrocarbons (TPH) - gasoline range organics (GRO: C6-C10) by United States Environmental Protection Agency (USEPA) Method 8260D, TPH - diesel range organics (DRO: C10-C28) and oil range organics (ORO: C28-C40) by USEPA Method 8015D, pH, specific conductance (EC), and SAR by saturated paste method, and boron by hot water soluble soil extract method. Analytical results indicated that constituent concentrations in soil sample WH-B01@5' were in compliance with the COGCC Table 915-1 standards, with exception to the SAR and EC results. Excavation and assessment activities are ongoing and will be summarized in a forthcoming Form 27-Supplemental Site Investigation and Remediation Workplan under Remediation Project No. 18260 (approved Form 27 Document No. 402697344). Based on the analytical results for sample WH-B01@5', confirmation soil samples will be analyzed for SAR and EC by saturated paste method. A topographic Site Location Map showing the geographic setting of the release is provided as Figure 1. Soil sample location and field screening data is provided in Table 1. Field notes and a photographic log are provided as Attachment A. The State Notification email is provided as Attachment B.</p>			
Soil/Geology Description:			
Clayey sand			
Depth to Groundwater (feet BGS) <u>20</u>		Number Water Wells within 1/2 mile radius: <u>6</u>	
If less than 1 mile, distance in feet to nearest	Water Well <u>1800</u> None <input type="checkbox"/>	Surface Water <u>940</u> None <input type="checkbox"/>	
	Wetlands _____ None <input checked="" type="checkbox"/>	Springs _____ None <input checked="" type="checkbox"/>	
	Livestock <u>3610</u> None <input type="checkbox"/>	Occupied Building <u>3830</u> None <input type="checkbox"/>	
Additional Spill Details Not Provided Above:			

## CORRECTIVE ACTIONS

#1 Supplemental Report Date: 06/17/2021

Root Cause of Spill/Release Unknown (Historical)

Other (specify) \_\_\_\_\_

Type of Equipment at Point of Spill/Release: Other

If "Other" selected above, specify or describe here:

Wellhead

Describe Incident & Root Cause (include specific equipment and point of failure)

Historical impacts were discovered following cut and cap operations at the wellhead.

Describe measures taken to prevent the problem(s) from reoccurring:

Site infrastructure has been removed and will not be replaced.

Volume of Soil Excavated (cubic yards): 40

Disposition of Excavated Soil (attach documentation)  Offsite Disposal  Onsite Treatment  
 Other (specify) \_\_\_\_\_

Volume of Impacted Ground Water Removed (bbls): \_\_\_\_\_

Volume of Impacted Surface Water Removed (bbls): \_\_\_\_\_

## REQUEST FOR CLOSURE

**Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.**

- Basis for Closure:
- Corrective Actions Completed (documentation attached, check all that apply)
    - Horizontal and Vertical extents of impacts have been delineated.
    - Documentation of compliance with Table 915-1 is attached.
    - All E&P Waste has been properly treated or disposed.
  - Work proceeding under an approved Form 27 (Rule 912.c).  
Form 27 Remediation Project No: 18260
  - SUSPECTED Spill/Release did not occur or was below Rule 912.a.(5) reporting thresholds.

## OPERATOR COMMENTS:

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: Gregory Hamilton

Title: Environmental Consultant Date: 06/17/2021 Email: Gregory\_Hamilton@oxy.com

## Condition of Approval

**COA Type****Description**

	Based on review of the information to be submitted in project 18260 which is ongoing at this time, it is concluded that the proposed investigation activities and proposed remedial actions in the approved site investigation and remediation plan will be adequate to remediate impacted soils at the site of the spill. However, should future conditions at the site indicate contaminant concentrations in soils exceeding COGCC standards or if ground water is found to be impacted, further site investigation and/or remediation activities may be required at the site.
1 COA	

### Attachment List

**Att Doc Num****Name**

402721862	SPILL/RELEASE REPORT(I/S)
402722455	SITE MAP
402722460	CORRESPONDENCE
402722461	PHOTO DOCUMENTATION
402722481	OTHER
402722860	FORM 19 SUBMITTED

Total Attach: 6 Files

### General Comments

**User Group****Comment****Comment Date**

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)