



WELLHEAD ABANDONMENT FORM

SITE NAME: Moser H 21-29							DATE: 6/10/2021	REM. PROJECT #:	WEATHER: partly cloudy 75		
SITE DIRECTIONS: CR32 and CR39 E 1.1, south into							CLIENT: Oxy				
LEGALS AND LAT/LONG: 40.2176995, -104.6730740							TASMAN PERSONNEL: Brandon LeVasseur				
SOIL TYPES: Silty Sand - SM							SURFACE GRADIENT: East				
SOIL SAMPLING							FACILITY INFRASTRUCTURE				
Date/Time	Soil Sample ID	PID (ppm)	Visual	Olfactory	Photo?	Grab or Lab Sample?	EQUIPMENT		Quantity		
							Above Ground Storage Tank (AST)				
6/10/2021 10:35	WH-B01 @6'	2.6	No Staining	No Odor	Yes	Lab	Buried or Partially Buried Vessel				
6/10/2021 10:37	WH-N01 @5'	2.8	No Staining	No Odor	Yes	N/A	Separator				
6/10/2021 10:39	WH-S01 @5'	1.1	No Staining	No Odor	Yes	N/A	Emission Control Device (ECD)				
6/10/2021 10:41	WH-E01 @5'	1.3	No Staining	No Odor	Yes	N/A	Dump Line				
6/10/2021 10:43	WH-W01 @5'	1.0	No Staining	No Odor	Yes	N/A	Wellhead		1		
6/10/2021 10:45	WHS-N01 @3"	1.0	No Staining	No Odor	Yes	N/A	Flowline		1		
6/10/2021 10:47	WHS-S01 @3"	1.0	No Staining	No Odor	Yes	N/A	Other:				
6/10/2021 10:49	WHS-E01 @3"	1.3	No Staining	No Odor	Yes	N/A	Soil Loads Removed				
6/10/2021 10:51	WHS-W01 @3"	1.2	No Staining	No Odor	Yes	N/A	IMPACTED SOIL IDENTIFIED?				
6/10/2021 10:53	WH-BG01 @6'	1.3	Organic Content	Organic Odor	Yes	Lab	ESTIMATED VOLUME OF IMPACTS:				
6/10/2021 10:54	FL-B01 @3'	0.9	No Staining	No Odor	Yes	N/A	Date		Number	CY	
							Total Removed		0	0	
							Disposal Facility:				
							Groundwater Recovery				
							DATE GW ENCOUNTERED:		DEPTH:		
							GROUNDWATER IN CONTACT WITH IMPACTED SOIL?				
							LNAPL OR SHEEN OBSERVED ON GW?				
GROUNDWATER SAMPLING							Date		BBLS		
Date/Time	Groundwater Sample ID	Depth Collected	Turbid?	Sheen?	Odor?	Photo?					
							Total Removed		0		
							Disposal Facility:				

Photographic Log


Equipment ID:		Equipment Type:		Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:		Material:	Volume:	Contents:	
Notes/Conditions: Background location 061021				Notes/Conditions: Soil sample and screening locations 061021			

Photographic Log

											
Equipment ID:		Equipment Type:		Equipment ID:		Equipment Type:					
Material:		Volume:		Contents:		Material:		Volume:		Contents:	
Notes/Conditions: Screening locations 061021						Notes/Conditions:					