


Location # 315261



location

**location**

XTO
T18-13G
Location # 315261



location



location

**XTO
T18-13G
Location # 315261**



Location/lack of battery signage



Lack of stabilization/compaction



XTO
T18-13G
Location # 315261



Lack of stabilization/compaction



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources