

Inspection Photos

API#081-06217

Operator: Jetta

Insp#: 692403503

Insp Date: 6/9/2021



Photo#1:

View North along Reclamation area on East side of road to vegetated area at North end.

June 9, 2021



Photo#2:
View to South from vegetated area to entry.

June 9, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Jetta PA Craig API#081-06217



Photo#3:
Reclamation area on West side of road.
*



Photo#4:
Reclamation area on East side of road. Fence
needs maintenance.

June 9, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Jetta PA Craig API#081-06217