

**Inspection Photos**  
**Location Name: Dry Creek Unit 3-22**  
**Location ID: 316758**



**Photo 1. Overview of location taken facing east.**



**Inspection Photos**  
**Location Name: Dry Creek Unit 3-22**  
**Location ID: 316758**



**Photo 2. Previous pumper on tanks as emergency contact number. NFPA diamonds becoming sun faded.**



**Photo 3. Previous pumper on one of two wellhead signs as emergency contact.**





**Inspection Photos**  
**Location Name: Dry Creek Unit 3-22**  
**Location ID: 316758**



**Photo 4. Tubing and apparent debris on location.**



**Photo 5. Wellhead sign two of two only spot on location with operator emergency contact.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



**Inspection Photos**  
**Location Name: Dry Creek Unit 3-22**  
**Location ID: 316758**



**Photo 6. No bradenhead access apparent. Stained soil at wellhead.**



**Photo 7. Stained soil at wellhead.**

