

Inspection Photos
Operator: Seeley Operating
API: 083-06532
Date: 6/17/2021



Photo 1. View the project area from the well pad entrance facing center.



Photo 2. View of the southern project area from the southeastern corner facing westward. Revegetation is progressing with western wheatgrass and intermediate wheatgrass.



Photo 3. View of the northern project area from the northeastern corner facing westward.



Photo 4/5. View of reference area(s) comprised of cultivated grass field (left) with western wheatgrass and intermediate wheatgrass, and pinyon and juniper woodland (right) with understory of sagebrush, penstemon, squirreltail, and snakeweed.