

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W /1NWSE

Location ID: 324063



Photo #4110 from entrance to location.



Photo #4111 from entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W /1NWSE

Location ID: 324063



Photo #4112 No battery sign located at the tank battery.



Photo #4113 Location lacks stabilization.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W /1NWSE

Location ID: 324063



Photo #4114 No form of tracking BMP located at the entrance to location.



Photo #4115 Access road lacks stabilization.