

Inspection Photos

6/21/2021

Operator: UTAH GAS OP LTD DBA UTAH GAS
CORP - 10539

Location ID: 323889
Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location ID: 323889



Photo 1: Photo taken from the west end of the Location, facing north. Photos 1-4 provide an overview of the Location from north, northeast, southeast to south. Photos show reclamation in process.



Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location ID: 323889



Photo 2: See comments under photo 1.



Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location ID: 323889



Photo 3: See comments under photo 1.



Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location ID: 323889



Photo 4: See comments under photo 1.

Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location ID: 323889



Photo 5: Photo of sign at Location entrance



Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location ID: 323889



Photo 6: Photo shows example of marked anchors on Location.

Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location ID: 323889



Photo 7: Photo taken from the eastern interim areas of the Location, facing north. Uniform shrub establishment observed on interim areas.

