

# Inspection Photos

6/21/2021

Operator: UTAH GAS OP LTD DBA UTAH GAS  
CORP - 10539

Location ID: 322317  
Garfield County, CO

Aaron Trujillo  
NW Reclamation Specialist  
COGCC

## Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location ID: 322317



20210621

**Photo 1:** Photo taken from the south end of the Location, facing west. Photos 1-4 provide an overview of the Location from west, northwest, northeast to east.

## Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location ID: 322317



**Photo 2:** See comments under photo 1.



## Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location ID: 322317



**Photo 3:** See comments under photo 1.

Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location ID: 322317



**Photo 4:** See comments under photo 1.

Inspection Photos  
Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539  
Location ID: 322317



Photo 5: Photo of signage at battery facility.

## Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location ID: 322317



**Photo 6:** Photo shows example of marked anchors on Location, as well as dominant vegetation on the interim areas.



## Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location ID: 322317



**Photo 7:** Photo taken from the wellhead; photo shows stained soils observed at base of well and riser; integrity concerns evident.



## Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location ID: 322317



**Photo 8:** Continued from photo 7. Photo shows integrity and leaking concerns are evident.

