

Inspection Photos

6/21/2021

Operator: FOUNDATION ENERGY
MANAGEMENT LLC - 10112

Location ID: 322320
Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC - 10112

Location ID: 322320



Photo 1: Photo taken from the south end of the Location, facing west. Photo shows meter shed.



Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC - 10112

Location ID: 322320



Photo 2: Photo taken from the south end of the Location, facing west. Photo shows compressor/separator/produced water tank equipment.



Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC - 10112

Location ID: 322320



Photo 3: Photo taken from the south end of the Location, facing east. Photo shows example of vegetation observed established on, and within the secondary containment BMP; vegetation establishment compromises the integrity and permeability of the containment BMP.



Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC - 10112

Location ID: 322320



Photo 4: Produced water tank.



Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC - 10112

Location ID: 322320



Photo 5: Photo shows unused pipe equipment/trash debris remaining on Location. Inspection #693802957 required compliance with Rule 606 and good housekeeping requirements; corrective action has not been addressed.



Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC - 10112

Location ID: 322320



Photo 6: Photo of signage at tank battery



Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC - 10112

Location ID: 322320



Photo 7: Photo of the tank battery on the southeast end of the Location. Photo also shows example of vegetation observed established on, and within the secondary containment BMP; vegetation establishment compromises the integrity and permeability of the containment BMP.



Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC - 10112

Location ID: 322320



Photo 8: Photo taken from the interim areas on the west end of the Location.

Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC - 10112

Location ID: 322320



Photo 10: Photo taken from the north end of the Location, facing South. Photo shows undesirable weedy plant establishment on the Location.