

Inspection Photos

6/21/2021

Operator: UTAH GAS OP LTD DBA UTAH GAS
CORP - 10539

Location ID: 322301
Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location ID: 322301



Photo 1: Photo taken from the west end of the Location, facing southwest. Photo provides an overview of the Location. Photo also shows undesirable weedy plant establishment on the production area.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location ID: 322301



Photo 2: Photo taken from the west end of the Location, facing northwest. Photo provides an overview of the Location. Photo also shows undesirable weedy plant establishment on the production area.



Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location ID: 322301



Photo 3: Photo shows example of marked anchors. Photo also shows undesirable weedy plant establishment on the production area.



Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location ID: 322301



Photo 4: Photo taken from the northern interim areas. Photo shows weed debris accumulation within vegetation.



Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location ID: 322301



Photo 5: Photo taken from the southern interim areas. Photo shows weed debris accumulation within vegetation.

