

Inspection Photos

6/21/2021

Operator: D & G ROUSTABOUT SERVICE

#22370

Location ID: 322318

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos

Operator Name: D & G ROUSTABOUT SERVICE #22370

Location ID: 322318



Photo 1: Photo taken from the north end of the Location, facing south. Undesirable weedy plant establishment observed on production areas, as well as around equipment.



Inspection Photos

Operator Name: D & G ROUSTABOUT SERVICE #22370

Location ID: 322318



Photo 2: Photo shows weed/plant establishment at the wellhead.



Inspection Photos
Operator Name: D & G ROUSTABOUT SERVICE #22370
Location ID: 322318



Photo 3: Photo shows weed/plant establishment at the separator and tank.

Inspection Photos

Operator Name: D & G ROUSTABOUT SERVICE #22370

Location ID: 322318



Photo 5: Photo shows noxious weed (Bindweed) establishment observed on the production areas of the Location.

Inspection Photos

Operator Name: D & G ROUSTABOUT SERVICE #22370

Location ID: 322318



Photo 6: Photo shows marked anchor on the southwest end of the Location.



Inspection Photos

Operator Name: D & G ROUSTABOUT SERVICE #22370

Location ID: 322318



Photo 7: Photo shows example of anchors on the Location not marked in accordance with 1003 rules.

