

Inspection Photos

6/21/2021

Operator: UTAH GAS OP LTD DBA UTAH GAS

CORP #10539

Location ID: 322353

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP #10539

Location ID: 322353



Photo 1: Photo taken from the south end of the Location, facing northwest. Photo provides an overview of the Location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP #10539

Location ID: 322353



Photo 2: Photo taken from the south end of the Location, facing northeast. Photo provides an overview of the Location. .



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP #10539

Location ID: 322353



Photo 3: Photo shows produced water tank. Tank capacity no longer identified.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP #10539

Location ID: 322353



Photo 4: Continued from photo 3. Photo shows tank capacity is no longer identified.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP #10539

Location ID: 322353



Photo 5: Photo shows example of marked anchors observed on Location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources