

Inspection Photos
Location Name: Klaenhammer 2
Location ID: 312862



Photo 1. Overview of location taken facing east.



Inspection Photos
Location Name: Klaenhammer 2
Location ID: 312862



Photo 2. Stained soil at wellhead.




Photo 3. Gas meter last calibrated 4/2019.