

Inspection Photos
Location Name: Klaenhammer 3
Location ID: 311767



Photo 1. Overview of location taken facing south.



Inspection Photos
Location Name: Klaenhammer 3
Location ID: 311767



Photo 2. No bradenhead access apparent.




Photo 3. Gas meter last calibrated 4/2019.



COLORADO
 Oil & Gas Conservation
 Commission
 Department of Natural Resources