

Inspection Photos
Location Name: Klaenhammer 3-A
Location ID: 311769



Photo 1. Overview of location taken facing south.



Inspection Photos
Location Name: Klaenhammer 3-A
Location ID: 311769



Photo 2. Stained soil at tank loadout.




Photo 3. Gas meter last calibrated 4/2019.