

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA-67S95W /6SEnw

Location ID: 334965



**Photo #4129 from entrance to location.**



**Photo #4130 from entrance to location.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA-67S95W /6SENW

Location ID: 334965



**Photo #4131 Location lacks stabilization.**



**Photo #4132 Location lacks stabilization.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA-67S95W /6SENW

Location ID: 334965



**Photo #4133 Location lacks stabilization.**



**Photo #4134 No form of tracking BMP located at entrance to location.**