

Inspection Photos

API#107-06206

Operator: North Finn

Insp#: 692403568

Insp Date: 6/4/2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to East.

Photo#2:
Lines, risers, debris on Location.

June 4, 2021



Photo#3:
Four marked anchors & sign remain on site.



Photo#4:
Lines, risers, debris on Location .

June 4, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: North Finn PA Breeze API#107-06206