

Inspection Photos

API: 009-06135

Operator: SOVEREIGN OPERATING COMPANY

Inspection Date: 6/21/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos



Photo 1. Facing southeast toward the location. The crop has not re-established at the abandoned well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06135 | Date: 6/21/2021

Inspection Photos



Photo 2. Facing south at the abandoned site. This area has not re-established a crop cover approximately 40'x40' area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06135 | Date: 6/21/2021

Inspection Photos



Photo 3. Facing northeast toward the surrounding undisturbed crop cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06135 | Date: 6/21/2021