

Inspection Photos  
Location Name: Clay 1  
Location ID: 321337



Photo 1 WH sign



Photo 2 WH

Inspection Photos  
Location Name: Clay 1  
Location ID: 321337




Photo 3 TB sign



Photo 4 TB

# Inspection Photos

Location Name: Clay 1  
Location ID: 321337



Photo 5 Gas Meter Run



Photo 6 Card in meter box indicates calibration is overdue



**Inspection Photos**  
**Location Name: Clay 1**  
**Location ID: 321337**



**Photo 7 Horizontal Heated Separator**