

# *Inspection Photos*

*API#045-09317*

*Operator: Terra*

*Insp#:692403576*

*Insp Date: 6/23/21*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Reclamation has been installed.

June 23, 2021



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra PA McBurney API#045-09317



Photo#2:  
Reclamation has been installed.

June 23, 2021



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra PA McBurney API#045-09317