

Inspection Photos
Location Name: Island Butte 2 #7-AH
API: 05-083-06542



Island Butte 2 #7-AH location photo.

Area of concern along SW edge of location.

Inspection Photos
Location Name: Island Butte 2 #7-AH
API: 05-083-06542



Horizontal heated treater in SW corner of location.



Location of Sample ID #0617211105.

Inspection Photos
Location Name: Island Butte 2 #7-AH
API: 05-083-06542



Location of Sample ID #0617211115.



Location of Sample ID #0617211130.