

Taproot – Briggsdale, CO Produced Water Release

Photo: 1

Description:

Facility located south of
the release location



Taproot – Briggsdale, CO Produced Water Release

Photo: 2

Description:

Initial impact observations
looking Northwest



Taproot – Briggsdale, CO Produced Water Release

Photo: 3

Description:

Impacted soil extent
looking east



Taproot – Briggsdale, CO Produced Water Release

Photo: 4

Description:

Removal of shallow
impacted soil north of the
release location



Taproot – Briggsdale, CO Produced Water Release

Photo: 5

Description:

Beginning Excavation of
release location



Taproot – Briggsdale, CO Produced Water Release

Photo: 6

Description:

Backfilled trench looking west after line repair



Taproot – Briggsdale, CO Produced Water Release

Photo: 7

Description:

Extent of Surface Scrape
looking North



Taproot – Briggsdale, CO Produced Water Release

Photo: 8

Description:

Borrow pit for backfilling of the excavation trench, looking southeast.

