

# *Inspection Photos*

*PA/AL Loc#437712*

*Operator: SWN*

*Insp#: 692403501*

*Insp Date: 6/9/2021*





Photo#1:  
Overview of Location to Southwest.

June 9, 2021



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: SWN PA/AL North Hayden Loc#437712





Photo#2:

Vegetation sparse in areas, not yet uniform across the site.

June 9, 2021





Photo#3:  
Access road, looking into Location.



Photo#4:  
Access road, looking out to County Road.

June 9, 2021





Photo#5:  
Weeds along access road.



Photo#6:  
Weeds along access road.

June 9, 2021