

Inspection Photos

API#103-07224

Operator: Cobra O&G

Insp#: 692403561

Insp Date: 6/17/2021




Photo#1:
Overview of Location from ridge road to Northwest.

June 17, 2021



Photo#2:
Pulled in view of Location from same point as Photo#1.

June 17, 2021



Photo#3:


Looking down on Location from Northwest ridge road; view to Northeast.

June 17, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Cobra O&G PA USA-McBride Inc #2 API#103-07224



Photo#5:
Aerial 1993.



Photo#6:
Aerial 2017

June 17, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Cobra O&G PA USA-McBride Inc #2 API#103-07224