

Inspection Photos

API#103-06383

Operator: Pioneer NR

Insp#: 692403562

Insp Date: 6/17/2021



Photo#1:
Overview of Location to Southwest.

June 17, 2021



Photo#2:
Road runs through site; view to Northeast. Insert is Pipe line identifying Marker on East edge of site.

June 17, 2021



Photo#3:
View along Cut slope.



Photo#4:
Electrical installation remains.

June 17, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Pioneer NR PA USA-McBride API#103-06383



Photo#5:
Concrete slab remains.



Photo#6:
Vegetated fill slope.

June 17, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Pioneer NR PA USA-McBride API#103-06383