

Inspection Photos

API#107-06189


Operator: North Finn

Insp#: 692403588

Insp Date: 6/24/2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1 #2 #3:
Eight anchors, debris, lines, risers have been removed.

June 24, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: North Finn PA Breeze API#107-06189