

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

06/28/2021

Submitted Date:

06/28/2021

Document Number:

699103944

FIELD INSPECTION FORM
 Loc ID 424781 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
424780	WELL	SI	06/01/2020	OW	123-34184	WILMOTH C 14-29	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Adequate

Corrective Action: _____ Date: _____

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 424780 Type: WELL API Number: 123-34184 Status: SI Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 04/25/2021Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 15 Fluid Type: _____End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

COGCC Comments

Comment

User

Date

COGCC Inspection Report Summary
 On Monday 6/28/21 at approximately 0943hrs I, Inspector Adam Burns,
 Conducted an on-site inspection at Wilmoth C 14-29 of Noble Energy
 Location ID: 424781 in Weld County, Colorado.
 While there, I observed a well that is PR.
 No violation of the COGCC rules were observed at the time of inspection.
 This is a summary of inspection report.

burnsa

06/28/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699103945	Inspection Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5465372