



Site Information	
Site	Riverbend 21-24
Date	4-2-2021
Sampler Name	Kendra Coreas
GEM 5000	6451

GEM Calibrations	
Calibration Gas	Time
Pure N2	12:30
Fresh Air	12:32
50 ppm CO, 10 ppm H2S	12:33
15% CH4, 15% CO2, Bal N2	12:35

Bump Test						
Time		CH4 (%)	CO2 (%)	O2 (%)	H2S (PPM)	CO (PPM)
12:52	Calibration Gas	15.0	15.0	0.0	0	0
	Readings	14.7	14.7	0.2	0	0

GEM Field Readings							
Well	CH4 (%)	CO2 (%)	O2 (%)	H2S (PPM)	CO (PPM)	Time	Comments
SUP01	0.0	0.5	20.5	0	0	13:03	
SUP02	0.0	0.5	16.0	0	0	13:07	
SUP03	0.0	0.3	15.8	0	0	13:14	
SUP04	0.0	0.2	18.7	0	0	13:19	

Site Notes and Observations (Surrounding vegetation, stressed or lack of vegetation, etc.)

Poor vegetation growth on entire pad.

Just mainly weeds