

Inspection Photos

API#045-22056

Operator: Terra

Insp#:692403604

Insp Date: 6/23/21



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location from entry to Southwest. Insert is road exiting location.

June 23, 2021



Photo#2:
Cut slope.

June 23, 2021



Photo#3:
Pad area.



Photo#4:
Pad area.

June 23, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra PA Morgan API#045-22056



Photo#5:

Fill slope, The white flower is native Yarrow, the yellow is White top with maturing seed heads.



Photo#6:

June 23, 2021



Photo#7:

White top, Scotch, Musk & Bull thistle. The white flower is native Yarrow, the yellow is White top with maturing seed heads.

Photo#8:

June 23, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra PA Morgan API#045-22056