

Final Reclamation Inspection

June 21, 2021

Operator: PDC ENERGY INC - 69175

Location ID: 330616

Inspection Document #:697503037

Weld County, CO

SENE Section 6 T5N R63W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: SKURICH ROTH #42-6
Location ID:330616



Photo 1. Photo taken from the eastern access road, facing West. Photo illustrates final reclamation has been performed. Establishment of desirable plant species was observed throughout the well location and access road.

Inspection Photos
Location Name: SKURICH ROTH #42-6
Location ID:330616



Photo 2. Photo taken from the well location/access road, facing West. See comments under Photo 1.

Inspection Photos
Location Name: SKURICH ROTH #42-6
Location ID:330616



Photo 3. Reference photo taken from the eastern access road, facing Southwest.

Inspection Photos

Location Name: SKURICH ROTH #42-6

Location ID:330616



Photo 4. Drone aerial imagery illustrates the tank battery, access road and well location.