

Final Reclamation Inspection

June 21, 2021

Operator: PDC ENERGY INC - 69175

Location ID: 323520

Inspection Document #:697503039

Weld County, CO

NESE Section 6 T5N R63W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: SKURICH-ROTHE #43-6
Location ID:323520



Photo 1. Photo taken from the northern access road, facing South. Photo illustrates final reclamation has been performed. Establishment of desirable plant species was observed throughout the access road.

Inspection Photos
Location Name: SKURICH-ROTHE #43-6
Location ID:323520



Photo 2. Photo taken from the northern access road, facing South. See comments under Photo 1.

Inspection Photos
Location Name: SKURICH-ROTHE #43-6
Location ID:323520



Photo 3. Reference photo taken west of the access road, facing South.