

# Inspection Photos

6/25/2021

Operator: CAERUS PICEANCE LLC # 10456

Location ID: 335573

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC # 10456  
Location ID: 335573



**Photo 1:** Photo taken from the northeast end of the Location, facing southeast. Photos 1-3 provide an overview of the pits and cuttings located on the southeast end of the Location from southeast, south to southwest.



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC # 10456  
Location ID: 335573



**Photo 2:** See comments under photo 1.





Inspection Photos  
Operator Name: CAERUS PICEANCE LLC # 10456  
Location ID: 335573



**Photo 3:** See comments under photo 1.





Inspection Photos  
Operator Name: CAERUS PICEANCE LLC # 10456  
Location ID: 335573



20210625

**Photo 4:** Photo of cuttings and pit on the southeast end of the Location, facing northwest.





## Inspection Photos

Operator Name: CAERUS PICEANCE LLC # 10456

Location ID: 335573



**Photo 5:** Photo of cuttings and pit, facing southeast.

