

Inspection Photos

6/25/2021

Operator: CAERUS PICEANCE LLC # 10456

Location ID: 335622

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos

Operator Name: CAERUS PICEANCE LLC # 10456

Location ID: 335622



Photo 1: Photo taken from the east end of the Location, facing south. Photos 1-4 provide an overview of the Location from south, southwest, northwest to north.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 335622



Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 335622



Photo 3: See comments under photo 1.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 335622



Photo 4: See comments under photo 1.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 335622



Photo 5: Photo taken from the production area around the wells, facing north. Photo shows noxious weed establishment (Halogeton) observed on the Location.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 335622



20210625

Photo 6: Continued from photo 5. Photo shows noxious weed establishment (Halogeton) observed on the Location.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 335622



Photo 7: Photo taken from the production areas on the east end of the Location. Photo shows noxious weed establishment (Halogeton, green plants) observed on the Location.