

Inspection Photos

Location Name: LARAMIE ENERGY LLC OXY Federal /0797-08-19 Pad

Location ID: 324339



Photo #4212 from entrance to location.



Photo #4213 No battery sign located at the tank battery.