

Inspection Photos

Location Name: LARAMIE ENERGY LLC Logan Wash /0796-16B Pad

Location ID: 324445



Photo #4227 from entrance to location.



Photo #4228 No battery sign located at the tank battery.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: LARAMIE ENERGY LLC Logan Wash /0796-16B Pad

Location ID: 324445



Photo #4229 Gully erosion occurring in access road ditch.



Photo #4230 Gully erosion occurring in access road ditch.

Inspection Photos

Location Name: LARAMIE ENERGY LLC Logan Wash /0796-16B Pad

Location ID: 324445



Photo #4231 No form of velocity check.



Photo #4232 No form of velocity check.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: LARAMIE ENERGY LLC Logan Wash /0796-16B Pad

Location ID: 324445



Photo #4233 Sediment accumulation at the corner of access road.

