

**Inspection Photos**  
**Location Name: Dunn 1-13H**  
**Location ID: 426458**




**Photo 1 – Pumping Unit**




**Photo 2 – Signage Refreshed on Tanks**



**Inspection Photos**  
**Location Name: Dunn 1-13H**  
**Location ID: 426458**



**Photo 3 – Signage Refreshed**



**Photo 4 – Loadline Leaking/Dripping out Fluid onto ground**





**Inspection Photos**  
**Location Name: Dunn 1-13H**  
**Location ID: 426458**



**Photo 5 – Tank Battery Sign**



**Photo 6 – Heater Treater, ECD and Flare**

