

Inspection Photos

Location name: TEP ROCKY MOUNTAIN LLC UNION-66S96W /33NWSE

Location ID: 335237



Photo #4262 from entrance to location.



Photo #4263 No tank battery sign located at the tank battery.



Inspection Photos

Location name: TEP ROCKY MOUNTAIN LLC UNION-66S96W /33NWSE

Location ID: 335237



Photo #4264 Location lacks stabilization.



Photo #4265 Location lacks stabilization.

Inspection Photos

Location name: TEP ROCKY MOUNTAIN LLC UNION-66S96W /33NWSE

Location ID: 335237



Photo #4266 No form of tracking BMP located at the entrance to location.




Photo #4267 Parachute creek from location.

Inspection Photos

Location name: TEP ROCKY MOUNTAIN LLC UNION-66S96W /33NWSE

Location ID: 335237



Approximate distance from location to Parachute creek.