

Inspection Photos
Location Name: Planck 1-14H
Location ID: 424707




Photo 1 – Wellhead – Stained Soil



Photo 2 – Tank Battery

Inspection Photos
Location Name: Planck 1-14H
Location ID: 424707



Photo 3 – Tank Battery Sign



Photo 4 – Heater Treater

Inspection Photos
Location Name: Planck 1-14H
Location ID: 424707



Photo 5 – ECDs



Photo 6 – Stained Soil at Gas Engine

Inspection Photos
Location Name: Planck 1-14H
Location ID: 424707



Photo 7 – Stained Soil at Gas Engine



Photo 8 – Stained Soil at Gas Engine