

**Inspection Photos**  
**Operator: Morningstar Res.**  
**API: 007-06261**  
**Date: 6/29/2021**



Photo 1. View the project area from the southeastern corner facing center.



Photo 2. View of the southern project area from the southeastern corner facing westward. Revegetation is progressing with crested wheatgrass, western wheatgrass, and rubber rabbitbrush.



Photo 3. View of reference area comprised of open field, with grasses such as western wheatgrass, and foxtail barley, forbs such as wormwood, sedges, and cattails.