

**Inspection Photos**  
**Operator: Morningstar Res.**  
**API: 007-06187**  
**Date: 6/29/2021**



Photo 1. View the project area from the northeastern corner facing center.



Photo 2. View the eastern project area from the northeastern corner facing southward.




Photo 3. View of kochia weed debris around tanks needs to be removed and properly disposed of.



Photo 4. View of reference area comprised of irrigated grass field with grasses such as western wheatgrass, and foxtail barley, forbs such as wormwood, sedges, and cattails.