

**Inspection Photos**  
**Operator: BP America**  
**API: 007-05004**  
**Date: 6/29/2021**



Photo 1. View the eastern project area facing northward. Vegetation is approximately the same as surrounding irrigated crop field.



Photo 2. View the project area from the southeastern corner facing center.



Photo 3. View of reference area comprised of irrigated grass field with grasses such as orchard grass, red fescue, and smooth brome.