

Inspection Photos

6/30/2021

Operator: EAGLE OPERATING INC #26155

Location ID: 397227

Rio Blanco County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: EAGLE OPERATING INC #26155
Location ID: 397227



Photo 1: Photo taken from the north end of the Location, facing east. Photos 1-4 provide an overview of the Location from east, southeast, southwest to west.



Inspection Photos
Operator Name: EAGLE OPERATING INC #26155
Location ID: 397227



June 30, 2021
40.11582316N 108.87179176W

Photo 2: See comments under photo 1.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: EAGLE OPERATING INC #26155
Location ID: 397227



Photo 3: See comments under photo 1.



Inspection Photos
Operator Name: EAGLE OPERATING INC #26155
Location ID: 397227



Photo 4: See comments under photo 1.



Inspection Photos
Operator Name: EAGLE OPERATING INC #26155
Location ID: 397227



June 30, 2021
40.0857257N 108.767707W

Photo 5: Photo shows example of noxious weed establishment observed on the Location.



Inspection Photos
Operator Name: EAGLE OPERATING INC #26155
Location ID: 397227



Photo 6: Photo shows example of noxious weed establishment observed on the Location.



Inspection Photos
Operator Name: EAGLE OPERATING INC #26155
Location ID: 397227



Photo 7: Photo of the transect #1, facing south.



Inspection Photos
Operator Name: EAGLE OPERATING INC #26155
Location ID: 397227



Photo 8: Photo shows soil surface for the 50th point of the 1st germination transect; desirable vegetative germination/establishment not observed, or negligible; approximately 1 seedling was observed for every 13 quadrats.



Inspection Photos
Operator Name: EAGLE OPERATING INC #26155
Location ID: 397227



Photo 10: Photo of the transect #2, facing south.



Inspection Photos
Operator Name: EAGLE OPERATING INC #26155
Location ID: 397227




Photo 11: Photo shows soil surface for the 50th point of the 2nd germination transect; desirable vegetative germination/establishment not observed, or negligible; approximately 1 seedling was observed for every 13 quadrats.

