

## Inspection Photos

Location Name: CAERUS PICEANCE LLC Mesa /E25-697

Location ID: 324389



Photo #4292 from entrance to location.



Photo #4293 from entrance to location.

## Inspection Photos

Location Name: CAERUS PICEANCE LLC Mesa /E25-697

Location ID: 324389



**Photo #4294 Location lack stabilization.**



**Photo #4295 No form of tracking BMP located at entrance to location.**