

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/23/2021

Submitted Date:

06/28/2021

Document Number:

700300183**FIELD INSPECTION FORM**Loc ID 325915 Inspector Name: LABOWSKIE, STEVE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 96735Name of Operator: WILLIFORD RESOURCES, L.L.C.Address: 6506 S LEWIS AVE STE 102City: TULSA State: OK Zip: 74136**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Williford, Hearne	918-712-8828	hwilli@swbell.net	
Stevens, Glenn	970-749-0192	glennstevens@centurylink.net	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215559	WELL	SI	08/12/2004	GW	067-07164	LONG & SCHLUTER 1 MENELEE	TA

General Comment:

Inspection for 5-year MIT witness to maintain TA status. Well is currently reported as shut in, CIB set, well not readily capable of production. Properly report well status as TA on monthly Form 7

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Rods and casing on location, cited in previous reports, not needed for ongoing operations		
Corrective Action:	remove unused equipment	Date:	08/28/2021

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	wellhead		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 215559 Type: WELL API Number: 067-07164 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: Well is not readily capable of production due to bridge plug and therefore in a state of temporarily abandonment and should be reported as "TA" on monthly Form 7s.

Mehcanical integrity test witness to maintain TA status. Starting pressure 330 psig, final pressure 325 psig after 20 min

Corrective Action: _____ Date: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402731452	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5465636
700300190	well sign and unused equipment	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5465629
700300191	gauge and unused equipment	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5465630