

Inspection Photos

Location Name: CAERUS PICEANCE LLC PUCKETT-66S97W /25NWNW

Location ID: 383295



Photo #4298 from entrance to location.



Photo #4299 from entrance to location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: CAERUS PICEANCE LLC PUCKETT-66S97W /25NWNW

Location ID: 383295



Photo #4300 Flow line heating insulation open ended and not capped.



Photo #4301 Unused battery next to separator.