

# Inspection Photos

API: 017-07634

Operator: PELICAN HILL OIL & GAS

Inspection Date: 6/9/2021



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 017-07634 | Date: 6/9/2021

## Inspection Photos



**Photo 1.** Facing north toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 017-07634 | Date: 6/9/2021

## Inspection Photos



**Photo 2.** Center of the location facing east. The area outlined contains mostly undesirable weeds consisting of Kochia sp. Flixweed, and Cheat grass.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 017-07634 | Date: 6/9/2021

## Inspection Photos



**Photo 3.** Center of the location facing west. The area outlined contains mostly undesirable weeds consisting of Kochia sp. Flixweed, and Cheat grass.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 017-07634 | Date: 6/9/2021

## Inspection Photos



**Photo 4.** View of groundcover at center of the location shows undesirable weed growth consisting of Kochia sp. Flixweed, and Cheat grass.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 017-07634 | Date: 6/9/2021

## Inspection Photos



**Photo 5.** Drone aerial photo looking down northeast toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

API: 017-07634 | Date: 6/9/2021

## Inspection Photos



**Photo 6.** Drone aerial photo looking down northwest toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

API: 017-07634 | Date: 6/9/2021

## Inspection Photos



**Photo 7.** Looking straight down at the location. The areas circled consists of predominately undesirable weeds as shown in previous photos.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 017-07634 | Date: 6/9/2021

## Inspection Photos



**Photo 8.** Drone image of the surrounding undisturbed field shows uniform vegetation cover.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 017-07634 | Date: 6/9/2021