

Inspection Photos  
Operator: Simcoe  
API: 067-08213  
Date: 7/2/2021



Photo 1. View the project area from the well pad entrance facing center.





Photo 2. View the western project area from the northwestern corner facing southward. Revegetation is progressing with western wheatgrass, crested wheatgrass, and sand dropseed.





Photos 3/4. View of Scotch thistles within the project area (approx. 15 rosettes observed).





Photo 5. View the reference area comprised of sagebrush shrubland with scattered pinyon and juniper trees and western wheatgrass, squirreltail, and penstemon in the understory.