

Inspection Photos

API: 055-06279

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 7/2/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 055-06279 | Date: 7/2/2021

Inspection Photos



Photo 1. Facing southwest toward the location. There is desirable vegetation cover throughout most of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06279 | Date: 7/2/2021

Inspection Photos



Photo 2. Facing northeast at the southeast side of location. There are a few Scotch thistle noxious weeds that need to be controlled.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06279 | Date: 7/2/2021

Inspection Photos



Photo 3. The northwest at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06279 | Date: 7/2/2021